




序号	报告编号	发布日期	结论	影像资料
172	GX-B1450/21-2-22050	2022. 5. 12	合格	
173	GX-B1450/21-2-22051	2022. 5. 12	合格	

174	GX-B1450/21-2-22052	2022. 5. 12	合格		
175	GX-B1450/21-2-22053	2022. 5. 12	合格		
176	GX-B1450/21-2-22054	2022. 5. 12	合格		

177	GX-B1310/21-2-22045	2022. 5. 11	合格		 <p>2022/4/20</p>	
178	GX-B1427/21-2-22045	2022. 5. 11	合格		 <p>2022/4/20</p>	
179	GX-B1310/21-2-22046	2022. 5. 11	合格		 <p>2022/4/25</p>	

180	GX-B1427/21-2-22046	2022. 5. 11	合格			
181	GX-B1310/21-2-22047	2022. 5. 11	合格			
182	GX-B1427/21-2-22047	2022. 5. 11	合格			

183	GX-B1310/21-2-22048	2022. 5. 11	合格		 <p>2022/4/25</p>	
184	GX-B1310/21-2-22049	2022. 5. 11	合格		 <p>2022/4/25</p>	
185	GX-B1450/21-2-22044	2022. 5. 12	合格		 <p>2022/4/9</p>	

186	GX-B1450/21-2-22045	2022. 5. 12	合格	
187	GX-B1450/21-2-22046	2022. 5. 12	合格	

188 GX-B1450/21-2-22047

2022. 5. 12

合格



189 GX-B1450/21-2-22048

2022. 5. 12

合格





190 GX-B1450/21-2-22049

2022. 5. 12

合格



191 GX-B1404/20-2-22005

2022. 5. 12

合格



192	GX-B1350/21-2-22046	2022. 5. 12	合格	 <p>2022.5.12</p>
193	GX-B1495/20-2-22443~22453	2022. 5. 13	合格	 <p>2022.5.13</p>

194 GX-B1300/20-2-22007

2022. 5. 13

合格



195 GX-B1300/20-2-22008

2022. 5. 13

合格



196	GX-B1328/20-2-22090	2022. 5. 17	合格	
-----	---------------------	-------------	----	---

197	GX-B1328/20-2-22091	2022. 5. 17	合格	
-----	---------------------	-------------	----	---

198 GX-B1328/20-2-22092

2022. 5. 17



合格









199	GX-B1328/20-2-22093	2022. 5. 17	合格	
-----	---------------------	-------------	----	---

200	GX-B1328/20-2-22094	2022. 5. 17	合格	 <p>A worker wearing a red hard hat, black jacket, and black pants is standing in an industrial room. In the foreground, there are yellow pipes and a black chair. The worker is positioned near a control panel or electrical cabinet. A date stamp '2022.5.17' is visible in the bottom right corner of the photo.</p>
201	GX-B1307/20-2-22006	2022. 5. 20	合格	 <p>An industrial structure with a corrugated metal roof and concrete pillars. The ground is dirt. A date stamp '2022-3-27' is visible on the ground in the foreground.</p>

202	GX-B1307/20-2-22007	2022. 5. 20	合格	
203	GX-B1307/20-2-22008	2022. 5. 20	合格	

204	GX-B1307/20-2-22009	2022. 5. 20	合格	
205	GX-B1307/20-2-22010	2022. 5. 20	合格	

206	GX-B1385/21-2-22014	2022. 5. 7	合格	
207	GX-B1404/20-2-22006	2022. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

208	GX-B1404/20-2-22007	2022. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
209	GX-B1354/20-2-22005	2022. 5. 19	电网接地电容电流符合规定。	

210	GX-B1450/21-2-22055	2022. 5. 20	合格	 
211	GX-B1450/21-2-22056	2022. 5. 20	合格	 