

序号	报告编号	发布日期	结论	影像资料
161	GX-B1404/20-1-22016	2022/8/19	合格	
162	GX-B1404/20-1-22017	2022/8/19	合格	
163	GX-B1306/21-1-22048	2022/8/19	合格	

164	GX-B1306/21-1-22049	2022/8/19	合格	
165	GX-B1306/21-1-22050	2022/8/19	合格	

166	GX-B1300/20-1-22005	2022/8/19	合格	
167	GX-B1304/21-1-22004	2022/8/19	合格	

168	GX-B1304/21-1-22005	2022/8/19	合格	
169	GX-B1304/21-1-22006	2022/8/19	合格	

170	GX-B1427/21-1-22070	2022. 8. 19	合格	 A photograph showing a worker in a blue uniform and red hard hat, wearing a safety harness, working on a large metal structure. The worker is positioned on a narrow platform or walkway. The background shows a dimly lit industrial environment with some equipment and a person in the distance. A date stamp '2022.8.19' is visible in the bottom right corner of the image.
171	GX-B1451/20-1-22411~22432	2022/8/19	合格	 A photograph showing a worker in a blue uniform and white hard hat, kneeling on the floor and working on a row of electrical cabinets. The worker is using a tool, possibly a screwdriver, to work on the front panel of one of the cabinets. The cabinets are white and have various labels and switches. A date stamp '2022.8.26' is visible in the bottom left corner of the image.

172	GX-B1451/20-1-22433~22458	2022/8/19	合格	
173	GX-B1451/20-1-22459~22476	2022/8/19	合格	



174	GX-B1415/22-1-22004	2022/8/22	合格	
175	GX-B1415/22-1-22005	2022/8/22	合格	

176	GX-B1415/22-1-22006	2022/8/22	合格	
177	GX-B1415/22-1-22007	2022/8/22	合格	



178	GX-B1415/22-1-22008	2022/8/22	合格	
179	GX-B1415/22-1-22009	2022/8/22	合格	

180	GX-B1310/21-1-22104	2022/8/22	合格	
181	GX-B1427/21-1-22104	2022/8/22	合格	

182	GX-B1310/21-1-22079	2022. 8. 19	合格	
183	GX-B1427/21-1-22079	2022. 8. 19	合格	

184	GX-B1310/21-1-22080	2022. 8. 19	合格		
185	GX-B1427/21-1-22080	2022. 8. 19	合格		

186	GX-B1310/21-1-22081	2022. 8. 19	合格		
187	GX-B1310/21-1-22082	2022. 8. 19	合格		

188	GX-B1427/21-1-22082	2022. 8. 19	合格			
189	GX-B1310/21-1-22083	2022. 8. 19	合格			