

序号	报告编号	发布日期	结论	影像资料
16	GX-B1601/22-B-22053~22056	2022. 11. 24	合格	
17	GX-B1593/21-B-220038~220039	2022. 11. 30	所检项目合格	

18	GX-B1372/22-B-220610~220618	2022. 11. 30	所检项目合格	 A photograph showing two workers in grey uniforms in a laboratory. One worker is standing at a blue counter, and the other is standing next to them. The counter has some equipment on it. The date stamp in the bottom right corner is 2022.10.1.
19	GX-B1374/22-B-220451~220457	2022. 11. 30	所检项目合格	 A photograph showing two workers in grey uniforms looking at equipment on a table. One worker is on the left, and the other is on the right. The equipment includes a power supply and some cables. The date stamp in the bottom right corner is 2022.10.1.
20	GX-B1601/22-B-22083	2022. 11. 30	合格	 A photograph showing a worker in a grey uniform and a blue face mask standing next to a large blue industrial machine. Another worker is visible in the background, sitting at a desk. The date stamp in the bottom right corner is 2022.11.25.

21	GX-B1601/22-B-22072~22076	2022. 11. 30	合格	
----	---------------------------	--------------	----	---