







序号	报告编号	发布日期	结论	影像资料
6	GX-B1340/21-9-22083	2022.12.8	所检项目合格	
7	GX-B1340/21-9-22084	2022.12.8	所检项目合格	
8	GX-B1371/21-9-22008	2022.12.7	除上述问题外，其余所检项目合格。	 
9	GX-B1343/21-9-22056	2022.12.8	/	
10	GX-B1347/21-9-22016	2022.12.8	/	

11	GX-B1341/21-9-22147	12.9	综合判定：合格。		
12	GX-B1341/21-9-22148	12.9	综合判定：合格。		
13	GX-B1341/21-9-22149	12.9	综合判定：合格。		
14	GX-B1370/21-9-22024	12.12	/		
15	GX-B1370/21-9-22025	12.9	/		
16	GX-B1343/21-9-22050	2022.12.13	/		

17	GX-B1345/21-9-22010	2022.12.13	/	
18	GX-B1346/21-9-22016	12.13	低瓦斯矿井	





