










序号	报告编号	发布日期	结论	影像资料
1	GX-B1517/20-6-22036	2023. 2. 1	综合判定：合格	 A close-up photograph of a worker wearing a red hard hat and a blue jacket, focused on inspecting a tunnel structure. The scene is dimly lit, with a bright light source illuminating the worker's face and the equipment they are using. A timestamp '2022 12 12' is visible in the bottom right corner of the image.
2	GX-B1517/20-6-22037	2023. 2. 1	综合判定：合格	 A photograph showing a worker in a purple jacket walking away from the camera down a tunnel. The tunnel is illuminated with red lights, creating a strong red glow. The worker is carrying a bag or equipment. A timestamp '2022 12 12' is visible in the bottom right corner of the image.
3	GX-B1517/20-6-22038	2023. 2. 1	综合判定：合格	 A photograph of a worker in a dark jacket walking through a tunnel. The tunnel is brightly lit with white lights, and the worker is carrying a bag. The tunnel walls are lined with pipes and equipment. A timestamp '2022 12 12' is visible in the bottom right corner of the image.





4	GX-B1517/20-6-22039	2023. 2. 1	综合判定：合格	
5	GX-B1517/20-6-22040	2023. 2. 1	综合判定：合格	
6	GX-B1322/21-6-22222~22229	2023. 2. 2	所检项目合格	
7	GX-B1415/22-6-23001	2023/2/6	所检项目合格	

8	GX-B1313/21-6-23004~23005	2023/2/3	合格		
9	GX-B1423/20-6-23009	2023/2/4			
10	GX-B1427/21-6-23004	2023/2/6	合格		
11	GX-B1427/21-6-23005	2023/2/6	合格		

12	GX-B1310/21-6-23009	2023/2/6	合格		
13	GX-B1310/21-6-23010	2023/2/6	合格		
14	GX-B1310/21-6-23003	2023/2/3	合格		
15	GX-B1310/21-6-23004	2023/2/3	合格		





16	GX-B1310/21-6-23005	2023/2/3	合格	
17	GX-B1427/21-6-23001	2023/2/3	合格	
18	GX-B1427/21-6-23002	2023/2/3	合格	
19	GX-B1354/20-6-22011	2023/2/6	合格	

20	GX-B1310/21-6-23006	2023/2/6	合格	
21	GX-B1310/21-6-23014	2023/2/7	合格	
22	GX-B1350/21-6-23002	2023/2/7	合格	
23	GX-B1301/21-6-23001	2023/2/7	合格	

24	GX-B1301/21-6-23002	2023/2/7	合格		
25	GX-B1520/20-6-23006	2023/2/7	合格		
26	GX-B1520/20-6-23005	2023/2/7	合格		
27	GX-B1300/20-6-23001	2023/2/8	合格		





28	GX-B1310/21-6-23014	2023/2/7	合格		
29	GX-B1515/22-6-23002	2023/2/7	合格		
30	GX-B1354/0-6-22011	2023/2/3	电网接地电容电流符合规定		
31	GX-B1415/22-6-23002	2023/2/8	合格		


32	GX-B1415/22-6-23003	2023/2/8	合格	
33	GX-B1520/20-6-23007	2023/2/9	综合判定：合格	
34	GX-B1520/20-6-23008	2023/2/9	综合判定：合格	
35	GX-B1520/20-6-23009	2023/2/9	综合判定：合格	

36	GX-B1424/20-6-23001	2023/2/8	合格	
37	GX-B1424/20-6-23002	2023/2/8	合格	
38	GX-B1350/21-6-23003	2023/2/10	所检项目合格	
39	GX-B1310/21-6-23007	2023/2/10	合格	

40	GX-B1310/21-6-23008	2023/2/10	合格		 <p>2023 01 26</p>	
41	GX-B1427/21-6-23003	2023/2/10	合格		 <p>2023 01 26</p>	
42	GX-B1310/21-6-23011	2023/2/10	合格		 <p>2023 01 08</p>	
43	GX-B1310/21-6-23012	2023/2/10	合格		 <p>2023 01 08</p>	

44	GX-B1310/21-6-23013	2023/2/10	合格		 2023 01 08	
45	GX-B1424/20-6-23003	2023/2/10	合格		 2023 01 16	
46	GX-B1424/20-6-23004	2023/2/10	合格		 2023 01 16	
47	GX-B1424/20-6-23005	2023/2/10	合格		 2023 01 16	

48	GX-B1424/20-6-23006	2023/2/10	合格	 A photograph showing workers in a tunnel environment. They are wearing red hard hats and dark clothing. One worker is pointing towards a large, curved, reddish-brown structure. The scene is dimly lit with some artificial light. A timestamp '2023 01 17' is visible in the bottom right corner of the photo.
49	GX-B1424/20-6-23007	2023/2/10	合格	 A photograph of a worker in a tunnel, wearing a red hard hat and dark jacket, kneeling and inspecting a large, curved, reddish-brown structure. The tunnel walls are visible in the background. A timestamp '2023 01 17' is visible in the bottom right corner of the photo.
50	GX-B1312/20-6-23001~23002	2023/2/13	合格	 A photograph of a worker in a workshop or factory setting. The worker is wearing a red hard hat, a grey jacket, and orange gloves, and is kneeling on the floor working on a large red cylindrical component. A timestamp '2023 02 13' is visible in the bottom right corner of the photo.
51	GX-B1328/20-6-23010	2023/2/13	合格	 A photograph of workers in an outdoor industrial setting. One worker is kneeling on the ground near a large, dark structure, possibly a piece of machinery or a container. Another worker is visible in the background. A timestamp '2023 02 13' is visible in the bottom right corner of the photo.

52	GX-B1328/20-6-23011	2023/2/13	合格		
53	GX-B1328/20-6-23012	2023/2/13	合格		
54	GX-B1328/20-6-23013	2023/2/13	合格	