










序号	报告编号	发布日期	结论	影像资料
225	GX-B1313/21-5-23019~23029	2023/2/17	本次共检电力变压器11台，11台所检项目合格。	 <p>The image block for row 225 contains six small photographs arranged in two rows of three. The top row shows close-up views of electrical equipment, possibly transformers, with some workers visible in the background. The bottom row shows workers in red hard hats and dark clothing performing inspection tasks on large electrical components, likely transformers, in an industrial setting.</p>
226	GX-B1329/21-5-23001~23030	2023/2/17	本次共检氧化锌避雷器30组，30组氧化锌避雷器所检项目合格。	 <p>The image block for row 226 contains a single photograph showing a worker wearing a dark blue protective suit with a clear face shield and a red hard hat. The worker is leaning over a piece of electrical equipment, possibly an arrester, on a green floor. A yellow and black striped safety line is visible in the background.</p>




227	GX-B1319/21-5-23120~23124	2023/2/20	<p>本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。</p>	
228	GX-B1451/20-5-23001~23028	2023/2/20	<p>本次共检高压开关柜28台，28台高压开关柜所检项目合格。</p>	
229	GX-B1451/20-5-23029~23042	2023/2/20	<p>本次共检高压开关柜14台，14台高压开关柜所检项目合格。</p>	

230	GX-B1319/21-5-23001~23030	2023/2/20	<p>本次共检高压交流断路器30台，30台高压交流断路器所检项目合格。</p>	
231	GX-B1319/21-5-23031~23044	2023/2/20	<p>合本次共检高压交流断路器14台，14台高压交流断路器所检项目合格。</p>	
232	GX-B1451/20-5-23079~23091	2023/2/20	<p>本次共检高压开关柜13台，13台高压开关柜所检项目合格。</p>	

233	GX-B1328/20-5-23022	2023. 2. 20	所检项目合格	
234	GX-B1328/20-5-23023	2023. 2. 20	所检项目合格	
235	GX-B1328/20-5-23024	2023. 2. 20	所检项目合格	

236	GX-B1328/20-5-23025	2023. 2. 20	所检项目合格	
237	GX-B1321/20-5-23277~23283	2023. 2. 20	所检项目合格	
238	GX-B1312/20-5-23125~23127	2023. 2. 20	所检项目合格	



239	GX-B1312/20-5-23128~23131	2023/2/17	本次共检电力变压器4台，4台电力变压器所检项目合格。	
240	GX-B1321/20-5-23284~23287	2023/2/17	本次共检电力电缆4条，4条电力电缆所检项目合格。	
241	GX-B1495/20-5-23495~23509	2023/2/20	本次共检高压开关柜15台，15台高压开关柜所检项目合格。	

242	GX-B1309/21-5-23010	2023/2/20	综合判定：合格。	 A worker wearing a red hard hat and a grey uniform is working in a confined space, possibly a tunnel or a large pipe. The worker is holding a tool or device. The date stamp in the bottom right corner of the photo is 2023/1/11.
243	GX-B1309/21-5-23011	2023/2/20	综合判定：合格。	 A worker wearing a red hard hat and a grey uniform is working in a confined space. The worker is holding a tool or device. The date stamp in the bottom right corner of the photo is 2023/1/11.
244	GX-B1309/21-5-23012	2023/2/20	综合判定：合格。	 A worker wearing a red hard hat and a grey uniform is standing on a ladder in a confined space. The worker is holding a tool or device. The date stamp in the bottom right corner of the photo is 2023/1/12.




245	GX-B1309/21-5-23013	2023/2/20	综合判定：合格。	
246	GX-B1500/21-5-23044	2023/2/20	综合判定：合格。	
247	GX-B1500/21-5-23045	2023/2/20	综合判定：合格。	




248	GX-B1500/21-5-23046	2023/2/20	综合判定：合格。	 A worker in a grey uniform and red helmet is working on a blue industrial machine. The worker is leaning over the machine, and there are various pipes and components visible. A yellow timestamp '2023/1/11' is in the bottom right corner.
249	GX-B1500/21-5-23047	2023/2/20	综合判定：合格。	 A worker in a grey uniform and red helmet is working on a blue industrial machine. The worker is leaning over the machine, and there are various pipes and components visible. A yellow timestamp '2023/1/11' is in the bottom right corner.
250	GX-B1500/21-5-23048	2023/2/20	综合判定：合格。	 A worker in a grey uniform and red helmet is working on a blue industrial machine. The worker is leaning over the machine, and there are various pipes and components visible. A yellow timestamp '2023/1/11' is in the bottom right corner.

251	GX-B1500/21-5-23049	2023/2/20	综合判定：合格。	
252	GX-B1500/21-5-23050	2023/2/20	综合判定：合格。	
253	GX-B1500/21-5-23051	2023/2/20	综合判定：合格。	

254	GX-B1500/21-5-23052	2023/2/20	综合判定：合格。	
255	GX-B1500/21-5-23053	2023/2/20	综合判定：合格。	
256	GX-B1500/21-5-23054	2023/2/20	综合判定：合格。	


257	GX-B1500/21-5-23055	2023/2/20	综合判定：合格。	
258	GX-B1500/21-5-23056	2023/2/20	综合判定：合格。	
259	GX-B1500/21-5-23057	2023/2/20	综合判定：合格。	

260	GX-B1500/21-5-23058	2023/2/20	综合判定：合格。	
261	GX-B1500/21-5-23059	2023/2/20	综合判定：合格。	
262	GX-B1500/21-5-23060	2023/2/20	综合判定：合格。	

263	GX-B1500/21-5-23061	2023/2/20	综合判定：合格。	
264	GX-B1500/21-5-23062	2023/2/20	综合判定：合格。	
265	GX-B1500/21-5-23063	2023/2/20	综合判定：合格。	

266	GX-B1304/21-5-23001	2023年2月20日	合格	
267	GX-B1310/21-5-23014	2023. 2. 17	所检项目合格	
268	GX-B1427/21-5-23002	2023. 2. 17	所检项目合格	

269	GX-B1310/21-5-23015	2023. 2. 17	所检项目合格	
270	GX-B1427/21-5-23001	2023. 2. 17	所检项目合格	
271	GX-B1310/21-5-23016	2023-2-17	符合标准要求。	

272	GX-B1427/21-5-23003	2023-2-17	符合标准要求。 。	
273	GX-B1499/21-5-23014, 23015, 23016	2023-2-21	所检项目合格。 。	