

序号	报告编号	发布日期	结论	影像资料
164	GX-B1517/20-2-23011	2023/3/28	所检项目合格	 A photograph showing a yellow forklift on a dirt path at a construction site. Three workers in dark clothing and red hard hats are standing around the forklift. In the background, there is a large, partially constructed building with a grey facade and some windows. A yellow timestamp '2023/3/5' is visible in the bottom right corner of the image.
165	GX-B1517/20-2-23012	2023/3/28	所检项目合格	 A photograph showing a worker in a dark jacket and red hard hat inspecting a yellow forklift. The forklift is parked on a dirt path. In the background, there is a yellow building with a red roof and some construction equipment. A yellow timestamp '2023/3/5' is visible in the bottom right corner of the image.

166	GX-B1517/20-2-23013	2023/3/28	所检项目合格	 A photograph showing a worker in a dark, underground tunnel. The worker is wearing a hard hat and a dark jacket, and is holding a clipboard. They are standing next to a piece of orange and black equipment, possibly a tunneling machine or a conveyor system. The tunnel walls are rough and rocky, and there are some lights visible in the background.
167	GX-B1517/20-2-23014	2023/3/28	所检项目合格	 A photograph showing a worker in a dark, underground tunnel. The worker is wearing a hard hat and a dark jacket, and is holding a clipboard. They are standing next to a piece of orange and black equipment, possibly a tunneling machine or a conveyor system. The tunnel walls are rough and rocky, and there are some lights visible in the background.

168	GX-B1517/20-2-23015	2023/3/28	所检项目合格	
169	GX-B1517/20-2-23016	2023/3/28	所检项目合格	