

序号	报告编号	发布日期	结论	影像资料
740	GX-B1417/22-Y-22083	2022年7月26日	合格	

741	GX-B1417/22-Y-22084	2022年7月26日	合格	 <p>A photograph showing two workers standing next to a metal cage. The worker on the left is wearing a light grey uniform and glasses. The worker on the right is wearing a dark blue uniform with a yellow scarf and a cap. The cage has a license plate that reads "#YK0011". The background shows an outdoor industrial area with a blue tarp and a building. A yellow date stamp "2022/7/9" is visible in the bottom right corner of the photo.</p>
742	GX-B1417/22-Y-22085	2022年7月26日	合格	 <p>A photograph showing two workers standing in front of a white truck. The worker on the left is wearing a light grey uniform, glasses, and a white face mask. The worker on the right is wearing a dark blue uniform with a yellow scarf and a cap. The truck has a large yellow number "3" on its front and a license plate that reads "#YK0003". The background shows an outdoor industrial area with a cloudy sky. A yellow date stamp "2022/7/9" is visible in the bottom right corner of the photo.</p>

743	GX-B1417/22-Y-22086	2022年7月26日	合格	 <p>A photograph showing two men standing in front of a white van. The man on the left is wearing a light-colored work shirt and pants, and the man on the right is wearing a dark blue work jacket and pants. The van has a large red number '2' on its front and a license plate that reads '桂Y K0002'. The background shows an outdoor industrial or construction site with a blue building and a cloudy sky. A yellow timestamp '2022/7/26' is visible in the bottom right corner of the photo.</p>
744	GX-B1417/22-Y-22087	2022年7月26日	合格	 <p>A photograph showing two men standing in front of a white truck. The man on the left is wearing a dark blue work jacket and pants, and the man on the right is wearing a light-colored work shirt and pants. The truck has a large red number '2' on its front and a license plate that reads '桂Y K0002'. The background shows an outdoor industrial or construction site with a blue building and a clear sky. A yellow timestamp '2022/7/26' is visible in the bottom right corner of the photo.</p>

745	GX-B1417/22-Y-22088	2022年7月26日	合格																							
746	GX-B1417/22-Y-22089	2022年7月26日	合格	 <table border="1" data-bbox="1256 927 1682 1198"> <thead> <tr> <th colspan="2">WC3Y(C) 防爆柴油机无轨胶轮车</th> </tr> <tr> <th colspan="2">WC3Y(C) Flameproof Diesel Trackless Rubber Tyred Vehicle</th> </tr> </thead> <tbody> <tr> <td>外形尺寸</td> <td>Main Dimension 4880 mm×1600 mm×1850 mm</td> </tr> <tr> <td>最大承载</td> <td>Max Payload 3 t</td> </tr> <tr> <td>车辆自重</td> <td>Weight 6.5 t</td> </tr> <tr> <td>发动机功率</td> <td>Max Power 65 kW</td> </tr> <tr> <td>运行速度</td> <td>Max Speed 0-14 km/h</td> </tr> <tr> <td>离地间隙</td> <td>Ground Clearance 170 mm</td> </tr> <tr> <td>出厂日期</td> <td>Manufacturing Date 2021.08</td> </tr> <tr> <td>出厂编号</td> <td>Manufacturing Code 21FB0563</td> </tr> <tr> <td colspan="2">山西天地煤机装备有限公司</td> </tr> </tbody> </table>	WC3Y(C) 防爆柴油机无轨胶轮车		WC3Y(C) Flameproof Diesel Trackless Rubber Tyred Vehicle		外形尺寸	Main Dimension 4880 mm×1600 mm×1850 mm	最大承载	Max Payload 3 t	车辆自重	Weight 6.5 t	发动机功率	Max Power 65 kW	运行速度	Max Speed 0-14 km/h	离地间隙	Ground Clearance 170 mm	出厂日期	Manufacturing Date 2021.08	出厂编号	Manufacturing Code 21FB0563	山西天地煤机装备有限公司	
WC3Y(C) 防爆柴油机无轨胶轮车																										
WC3Y(C) Flameproof Diesel Trackless Rubber Tyred Vehicle																										
外形尺寸	Main Dimension 4880 mm×1600 mm×1850 mm																									
最大承载	Max Payload 3 t																									
车辆自重	Weight 6.5 t																									
发动机功率	Max Power 65 kW																									
运行速度	Max Speed 0-14 km/h																									
离地间隙	Ground Clearance 170 mm																									
出厂日期	Manufacturing Date 2021.08																									
出厂编号	Manufacturing Code 21FB0563																									
山西天地煤机装备有限公司																										

747	GX-B1417/22-Y-22090	2022年7月26日	合格	
748	GX-B1417/22-Y-22091	2022年7月26日	合格	

749	GX-B1417/22-Y-22092	2022年7月26日	合格	
750	GX-B1417/22-Y-22093	2022年7月26日	合格	

751	GX-B1300/20-Y-22010	2022年7月26日	合格	
752	GX-B1415/22-Y-22016	2022年7月26日	合格	

753	GX-B1428/21-Y-22112	2022年7月26日	合格	
754	GX-B1428/21-Y-22113	2022年7月26日	合格	

755	GX-B1521/20-Y-22045	2022年7月26日	合格	
-----	---------------------	------------	----	---

756	GX-B1521/20-Y-22046	2022年7月26日	合格	
-----	---------------------	------------	----	---

757 GX-B1521/20-Y-22047

2022年7月26日

合格



758	GX-B1521/20-Y-22048	2022年7月26日	合格	 <p>A yellow Sdlg 12 excavator is shown at a construction site. A worker in a white shirt and red hard hat stands in the foreground. The excavator's arm is raised, and the bucket is positioned near a concrete structure. The date stamp '2022/7/20' is visible in the bottom right corner of the image.</p>
759	GX-B1423/20-Y-222931	2022年7月26日	合格	 <p>A yellow MT88H dump truck is shown at a construction site. Two workers in safety gear stand in front of the truck. The license plate number '东 B378' is visible on the side of the truck. The date stamp '2022/7/16' is visible in the bottom right corner of the image.</p>

760	GX-B1423/20-Y-222932	2022年7月26日	合格	
761	GX-B1423/20-Y-222933	2022年7月26日	合格	

762	GX-B1423/20-Y-222934	2022年7月26日	合格	
763	GX-B1423/20-Y-222935	2022年7月26日	合格	

764	GX-B1423/20-Y-222936	2022年7月26日	合格	
765	GX-B1539/22-Y-22160	2022年7月26日	合格	

766	GX-B1539/22-Y-22161	2022年7月26日	合格	
767	GX-B1539/22-Y-22162	2022年7月26日	合格	

768	GX-B1539/22-Y-22163	2022年7月26日	合格	
769	GX-B1539/22-Y-22164	2022年7月26日	合格	

770	GX-B1312/20-Y-22288	2022年7月26日	合格	
771	GX-B1499/21-Y-22119	2022年7月26日	合格	

772	GX-B1499/21-Y-22120	2022年7月26日	合格	
-----	---------------------	------------	----	---

773	GX-B1499/21-Y-22121	2022年7月26日	合格	
-----	---------------------	------------	----	---

774	GX-B1499/21-Y-22122	2022年7月26日	合格	
-----	---------------------	------------	----	---

775	GX-B1499/21-Y-22123	2022年7月26日	合格	 <p>A photograph showing a construction site in a mountainous area. Two workers are visible near a large, orange-colored pipe. The ground is rocky and uneven. A yellow date stamp '2022/7/15' is present in the bottom right corner of the image.</p>
776	GX-B1499/21-Y-22124	2022年7月26日	合格	 <p>A photograph showing a worker in a light-colored uniform standing at a construction site. The worker is looking at a device or document. A large pipe is visible on the ground. The background shows a rocky, mountainous landscape. A yellow date stamp '2022/7/15' is present in the bottom right corner of the image.</p>

777	GX-B1499/21-Y-22127	2022年7月27日	合格	 A photograph showing a construction site in a mountainous area. A worker in a white shirt and dark pants is standing near a green piece of machinery. The ground is covered with dark soil and rocks. A string of colorful triangular flags (red, yellow, blue, green) is strung across the site. A date stamp '2022/7/19' is visible in the bottom right corner of the image.
778	GX-B1499/21-Y-22128	2022年7月27日	合格	 A photograph of a green truck with the Chinese characters '三矿山' and '原煤业' (San Kuang Shan Yuan Mo Ye) on its side. The truck is parked on a muddy, rocky ground. A worker is visible near the truck. A string of colorful triangular flags is strung across the site. A date stamp '2022/7/19' is visible in the bottom right corner of the image.

779	GX-B1499/21-Y-22129	2022年7月27日	合格	
780	GX-B1499/21-Y-22125	2022年7月26日	合格	

781	GX-B1499/21-Y-22126	2022年7月26日	合格	
782	GX-B1423/20-Y-222896	2022年7月26日	合格	

783	GX-B1423/20-Y-222897	2022年7月26日	合格	
784	GX-B1423/20-Y-222898	2022年7月26日	合格	

785	GX-B1423/20-Y-222899	2022年7月26日	合格	 A yellow dump truck is parked on a dark, muddy surface. Two workers in safety gear are standing next to it. The truck has "7311" and "7311" written on its side. A date stamp "2022/7/12" is visible in the bottom right corner of the photo.
786	GX-B1423/20-Y-222900	2022年7月26日	合格	 A yellow dump truck is parked on a dark, muddy surface. Two workers in safety gear are standing next to it. The truck has "7311" and "7311" written on its side. A date stamp "2022/7/12" is visible in the bottom right corner of the photo.

787	GX-B1423/20-Y-222901	2022年7月26日	合格	 <p>A yellow XG10E dump truck is shown from a front-three-quarter view. The truck has the number '1005' painted on its side. Two people are standing in front of the truck. The background shows a dark, rocky surface, likely a mine. A yellow timestamp '2022/7/12' is visible in the bottom right corner of the photo.</p>
788	GX-B1423/20-Y-222902	2022年7月26日	合格	 <p>A yellow XG10E dump truck is shown from a front-three-quarter view. The truck has the number '1009' painted on its side. Three people are standing in front of the truck. The background shows a dark, rocky surface, likely a mine. A yellow timestamp '2022/7/12' is visible in the bottom right corner of the photo.</p>

789	GX-B1423/20-Y-222903	2022年7月26日	合格	
790	GX-B1423/20-Y-222904	2022年7月26日	合格	

791	GX-B1423/20-Y-222905	2022年7月26日	合格	
792	GX-B1539/22-Y-22148	2022年7月26日	合格	

793	GX-B1539/22-Y-22149	2022年7月26日	合格	
794	GX-B1539/22-Y-22150	2022年7月26日	合格	

795	GX-B1539/22-Y-22151	2022年7月26日	合格	
796	GX-B1539/22-Y-22152	2022年7月26日	合格	

797	GX-B1539/22-Y-22153	2022年7月26日	合格	
798	GX-B1539/22-Y-22154	2022年7月26日	合格	

799	GX-B1539/22-Y-22159	2022年7月26日	合格	
800	GX-B1423/20-Y-222911	2022年7月26日	合格	

801	GX-B1423/20-Y-222912	2022年7月26日	合格	
802	GX-B1423/20-Y-222913	2022年7月26日	合格	

803	GX-B1423/20-Y-222914	2022年7月26日	合格	
804	GX-B1423/20-Y-222915	2022年7月26日	合格	

805	GX-B1423/20-Y-222916	2022年7月26日	合格	
806	GX-B1423/20-Y-222917	2022年7月26日	合格	

807	GX-B1423/20-Y-222918	2022年7月26日	合格	
808	GX-B1423/20-Y-222919	2022年7月26日	合格	

809	GX-B1423/20-Y-222920	2022年7月26日	合格	
810	GX-B1423/20-Y-222921	2022年7月26日	合格	

811	GX-B1423/20-Y-222922	2022年7月26日	合格	
812	GX-B1423/20-Y-222923	2022年7月26日	合格	

813	GX-B1423/20-Y-222924	2022年7月26日	合格	
814	GX-B1423/20-Y-222925	2022年7月26日	合格	

815	GX-B1423/20-Y-222926	2022年7月26日	合格	
816	GX-B1423/20-Y-222927	2022年7月26日	合格	

817	GX-B1423/20-Y-222928	2022年7月26日	合格	
818	GX-B1423/20-Y-222929	2022年7月26日	合格	

819	GX-B1423/20-Y-222930	2022年7月26日	合格	
820	GX-B1539/22-Y-22155	2022年7月26日	合格	

821	GX-B1539/22-Y-22156	2022年7月26日	合格	
822	GX-B1539/22-Y-22157	2022年7月26日	合格	

823	GX-B1539/22-Y-22158	2022年7月26日	合格	
824	GX-B1321/20-Y-22369~22374	2022年7月26日	合格	

825	GX-B1321/20-Y-22375~22380	2022年7月26日	合格	
826	GX-B1310/21-Y-22114	2022年7月26日	合格	

827	GX-B1310/21-Y-22115	2022年7月26日	合格	
828	GX-B1428/21-Y-22116	2022年7月27日	合格	

829	GX-B1428/21-Y-22117	2022年7月26日	合格	
830	GX-B1310/21-Y-22116	2022年7月27日	合格	

831	GX-B1310/21-Y-22117	2022年7月27日	合格	 <p>A photograph showing two workers in an industrial setting. One worker is wearing a black t-shirt with 'H&M' on it, and the other is wearing a grey work shirt and a red hard hat. They are standing in a narrow aisle between large blue metal structures. A yellow date stamp '2022/7/11' is visible in the bottom right corner of the photo.</p>
832	GX-B1404/20-Y-22012	2022年7月27日	合格	 <p>A photograph of a worker in a grey uniform with '中檢心機' (Zhongjian Xinji) on the back, working in a control room. The worker is standing in front of a large panel with various controls and displays. A yellow date stamp '2022/6/28' is visible in the bottom right corner of the photo.</p>