

| 序号 | 报告编号                | 发布日期       | 结论      | 影像资料   |
|----|---------------------|------------|---------|--|
| 74 | GX-B1561/20-Y-23001 | 2023年3月14日 | 所检项目合格。 |   |
| 75 | GX-B1561/20-Y-23002 | 2023年3月14日 | 所检项目合格。 |   |
| 76 | GX-B1561/20-Y-23003 | 2023年3月14日 | 所检项目合格。 |  |

|    |                     |            |         |   |
|----|---------------------|------------|---------|---|
| 77 | GX-B1561/20-Y-23004 | 2023年3月14日 | 所检项目合格。 |    |
| 78 | GX-B1561/20-Y-23005 | 2023年3月14日 | 所检项目合格。 |    |
| 79 | GX-B1522/20-Y-23011 | 2023年3月14日 | 所检项目合格。 |   |
| 80 | GX-B1522/20-Y-23012 | 2023年3月14日 | 所检项目合格。 |  |

|    |                     |            |         |   |
|----|---------------------|------------|---------|---|
| 81 | GX-B1522/20-Y-23013 | 2023年3月14日 | 所检项目合格。 |    |
| 82 | GX-B1522/20-Y-23014 | 2023年3月14日 | 所检项目合格。 |    |
| 83 | GX-B1522/20-Y-23015 | 2023年3月14日 | 所检项目合格。 |   |
| 84 | GX-B1522/20-Y-23016 | 2023年3月14日 | 所检项目合格。 |  |

|    |                     |            |         |   |
|----|---------------------|------------|---------|---|
| 85 | GX-B1522/20-Y-23017 | 2023年3月14日 | 所检项目合格。 |    |
| 86 | GX-B1522/20-Y-23018 | 2023年3月14日 | 所检项目合格。 |    |
| 87 | GX-B1522/20-Y-23019 | 2023年3月14日 | 所检项目合格。 |   |
| 88 | GX-B1522/20-Y-23020 | 2023年3月14日 | 所检项目合格。 |  |

|    |                     |            |         |  |
|----|---------------------|------------|---------|--|
| 89 | GX-B1522/20-Y-23021 | 2023年3月14日 | 所检项目合格。 |  A photograph showing a person in a blue uniform operating a yellow excavator. The person is visible through the glass of the cab. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the image.               |
| 90 | GX-B1522/20-Y-23022 | 2023年3月14日 | 所检项目合格。 |  A photograph of a person wearing a grey uniform and a red hard hat, inspecting a piece of heavy machinery. The person is holding a blue folder. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the image. |
| 91 | GX-B1522/20-Y-23023 | 2023年3月14日 | 所检项目合格。 |  A photograph showing a person in a grey uniform and red hard hat inspecting a large piece of machinery with a red '20' on its side. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the image.            |
| 92 | GX-B1522/20-Y-23024 | 2023年3月14日 | 所检项目合格。 |  A photograph of a person in a grey uniform and red hard hat inspecting a piece of machinery. The person is holding a blue folder. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the image.             |

|    |                     |            |   |   |
|----|---------------------|------------|---|---|
| 93 | GX-B1522/20-Y-23025 | 2023年3月14日 | 所检项目合格。   |    |
| 94 | GX-B1310/21-Y-23011 | 2023年3月16日 | 符合标准要求。   |    |
| 95 | GX-B1424/20-Y-23002 | 2023年3月16日 | 依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。 |   |
| 96 | GX-B1522/20-Y-23026 | 2023年3月16日 | 所检项目合格。   |  |

|    |                     |            |         |  |
|----|---------------------|------------|---------|--|
| 97 | GX-B1522/20-Y-23027 | 2023年3月16日 | 所检项目合格。 |   |
| 98 | GX-B1417/22-Y-23015 | 2023年3月17日 | 所检项目合格  |   |
| 99 | GX-B1417/22-Y-23017 | 2023年3月17日 | 所检项目合格  |  |

|     |                     |            |        |  |
|-----|---------------------|------------|--------|--|
| 100 | GX-B1350/21-Y-23003 | 2023年3月17日 | 所检项目合格 |   |
| 101 | GX-B1350/21-Y-23004 | 2023年3月17日 | 所检项目合格 |  |



|     |                     |            |         |   |
|-----|---------------------|------------|---------|---|
| 102 | GX-B1350/21-Y-23005 | 2023年3月17日 | 所检项目合格  |  A photograph showing two workers wearing red hard hats and work clothes. They are crouching on a concrete surface, inspecting some equipment or wires. A yellow date stamp '2023/3/17' is visible in the bottom left corner of the image.   |
| 103 | GX-B1423/20-Y-23533 | 2023年3月10日 | 综合判定：合格 |  A photograph of a yellow dump truck. The truck has '天大地大 安全第一' (Safety First, Great Earth, Great Sky) written in red on the side, and the number '66' in a red circle. Two workers in work clothes are standing in front of the truck. A yellow date stamp '2023/2/21' is visible in the bottom right corner of the image. |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 104 | GX-B1423/20-Y-23534 | 2023年3月10日 | 综合判定：合格 |   |
| 105 | GX-B1423/20-Y-23531 | 2023年3月10日 | 综合判定：合格 |  |

|     |                     |            |  |   |
|-----|---------------------|------------|--|---|
| 106 | GX-B1423/20-Y-23532 | 2023年3月10日 | 综合判定：合格  |    |
| 107 | GX-B1404/20-Y-23001 | 2023年3月17日 | <p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p> |   |
| 108 | GX-B1404/20-Y-23002 | 2023年3月17日 | <p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p> |  |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 109 | GX-B1385/21-Y-23006 | 2023年3月15日 | 所检项目合格。 |   |
| 110 | GX-B1385/21-Y-23007 | 2023年3月14日 | 所检项目合格。 |  |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 111 | GX-B1385/21-Y-23008 | 2023年3月14日 | 所检项目合格。 |   |
| 112 | GX-B1385/21-Y-23009 | 20233/3/15 | 所检项目合格。 |  |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 113 | GX-B1385/21-Y-23010 | 2023年3月15日 | 所检项目合格。 |  A worker wearing a red hard hat, a white protective suit, and a white face mask stands in an industrial environment. The worker is holding a device, possibly a detector or a tool. The background shows industrial machinery and structures. A yellow timestamp '2023/2/23' is visible in the bottom right corner of the photo.   |
| 114 | GX-B1385/21-Y-23011 | 2023年3月15日 | 所检项目合格。 |  A worker wearing a red hard hat, a white protective suit, and a white face mask is working on a large, dark industrial component. The worker is using a tool, possibly a flashlight or a detector, to inspect the component. The background shows industrial machinery and structures. A yellow timestamp '2023/2/24' is visible in the bottom right corner of the photo. |

|     |                     |            |         |   |
|-----|---------------------|------------|---------|---|
| 115 | GX-B1385/21-Y-23012 | 2023年3月15日 | 所检项目合格。 |  A worker wearing a red hard hat and a grey uniform is standing in an industrial setting. He is holding a vertical measuring tool against a metal structure. The date '2023/2/24' is visible in the bottom right corner of the photo.                            |
| 116 | GX-B1385/21-Y-23013 | 2023年3月15日 | 所检项目合格。 |  A worker wearing a red hard hat and a grey uniform is standing in an industrial setting. He is holding a handheld device, possibly a tablet or a specialized tool, and looking at it. The date '2023/2/24' is visible in the bottom right corner of the photo. |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 117 | GX-B1385/21-Y-23014 | 2023年3月15日 | 所检项目合格。 |   |
| 118 | GX-B1385/21-Y-23015 | 2023年3月15日 | 所检项目合格。 |  |



|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 119 | GX-B1385/21-Y-23016 | 2023年3月15日 | 所检项目合格。 |   |
| 120 | GX-B1385/21-Y-23017 | 2023年3月15日 | 所检项目合格。 |  |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 121 | GX-B1385/21-Y-23018 | 2023年3月15日 | 所检项目合格。 |   |
| 122 | GX-B1385/21-Y-23019 | 2023年3月15日 | 所检项目合格。 |  |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 123 | GX-B1385/21-Y-23020 | 2023年3月15日 | 所检项目合格。 |  <p>A photograph showing a worker in a red hard hat and grey uniform inspecting a large industrial structure. The worker is holding a device, possibly a tablet or a camera. The structure is made of metal and has a complex, curved design. The date stamp in the bottom right corner of the photo is 2023/2/25.</p>  |
| 124 | GX-B1385/21-Y-23021 | 2023年3月16日 | 所检项目合格。 |  <p>A photograph showing a worker in a red hard hat and grey uniform inspecting a large industrial structure. The worker is holding a device, possibly a tablet or a camera. The structure is made of metal and has a complex, curved design. The date stamp in the bottom right corner of the photo is 2023/2/26.</p> |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 125 | GX-B1385/21-Y-23022 | 2023年3月16日 | 所检项目合格。 |   |
| 126 | GX-B1385/21-Y-23023 | 2023年3月16日 | 所检项目合格。 |  |

|     |                     |            |         |   |
|-----|---------------------|------------|---------|---|
| 127 | GX-B1385/21-Y-23024 | 2023年3月16日 | 所检项目合格。 |  A worker wearing a red hard hat, a grey jacket, and a white face mask is inspecting a large metal structure at night. The worker is holding a long metal rod or tool. The scene is illuminated by a bright light source, possibly a work lamp. A yellow timestamp "2023/2/26" is visible in the bottom right corner of the photo.                             |
| 128 | GX-B1385/21-Y-23026 | 2023年3月17日 | 所检项目合格。 |  A worker wearing a red hard hat, a grey jacket, and a white face mask is inspecting a large metal structure in a factory or industrial setting. The worker is holding a small device, possibly a measuring tool or a camera. The scene is illuminated by overhead lights. A yellow timestamp "2023/2/27" is visible in the bottom right corner of the photo. |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 129 | GX-B1385/21-Y-23027 | 2023年3月17日 | 所检项目合格。 |   |
| 130 | GX-B1385/21-Y-23028 | 2023年3月17日 | 所检项目合格。 |  |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 131 | GX-B1385/21-Y-23029 | 2023年3月17日 | 所检项目合格。 |  A worker wearing a red hard hat, a grey protective suit, and a white respirator mask is working on a large industrial machine. The worker is holding a tool and appears to be inspecting or adjusting a part of the machinery. The background shows an industrial setting with windows and structural elements. A yellow timestamp '2023/3/17' is visible in the bottom right corner of the photo. |
| 132 | GX-B1385/21-Y-23030 | 2023年3月17日 | 所检项目合格。 |  A worker wearing a red hard hat, a grey protective suit, and a white respirator mask is standing on a metal platform. The worker is holding a clipboard and looking at a large blue industrial machine. The background shows an outdoor industrial setting with a clear sky. A yellow timestamp '2023/3/17' is visible in the bottom right corner of the photo.                                   |

|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 133 | GX-B1385/21-Y-23031 | 2023年3月17日 | 所检项目合格。 |   |
| 134 | GX-B1385/21-Y-23032 | 2023年3月17日 | 所检项目合格。 |  |



|     |                     |            |         |  |
|-----|---------------------|------------|---------|--|
| 135 | GX-B1385/21-Y-23033 | 2023年3月17日 | 所检项目合格。 |  <p>A worker wearing a red hard hat, a white face mask, and a grey protective suit is inspecting a metal structure outdoors. The worker is holding a clipboard and looking at it. The background shows a blue metal frame and some industrial equipment. A yellow timestamp '2023/2/28' is visible in the bottom right corner of the photo.</p> |
| 136 | GX-B1385/21-Y-23034 | 2023年3月17日 | 所检项目合格。 |  <p>A worker wearing a red hard hat, a white face mask, and a grey protective suit is inspecting a metal structure indoors. The worker is holding a clipboard and looking at it. The background shows a blue metal frame and some industrial equipment. A yellow timestamp '2023/2/28' is visible in the bottom right corner of the photo.</p> |

|     |                     |            |  |  |
|-----|---------------------|------------|--|--|
| 137 | GX-B1539/22-Y-23012 | 2023年3月20日 | 所检项目合格。  |   |
| 138 | GX-B1539/22-Y-23013 | 2023年3月20日 | 所检项目合格。  |   |
| 139 | GX-B1521/20-Y-23039 | 2023年3月20日 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》<br/>GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》<br/>》，所检项目合格。</p> |  |

|     |                     |            |  |   |
|-----|---------------------|------------|--|---|
| 140 | GX-B1521/20-Y-23040 | 2023年3月20日 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》<br/>GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》<br/>》，所检项目合格。</p> |  |
| 141 | GX-B1521/20-Y-23041 | 2023年3月20日 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》<br/>GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》<br/>》，所检项目合格。</p> |  |