










序号	报告编号	发布日期	结论	影像资料
41	GX-B1307/20-3-23013	2023年5月6日	所检项目合格	 A worker wearing a grey uniform and a red hard hat is inspecting a piece of industrial equipment. The worker is leaning over the equipment, and the scene is set in an industrial environment. A timestamp '2023.4.21' is visible in the bottom right corner of the image.
42	GX-B1307/20-3-23014	2023年5月6日	所检项目合格	 Two workers wearing grey uniforms and red hard hats are inspecting a piece of industrial equipment. One worker is holding a white cylindrical object, possibly a component or a tool, and is showing it to the other worker. The scene is set in an industrial environment. A timestamp '2023.4.21' is visible in the bottom right corner of the image.
43	GX-B1307/20-3-23015	2023年5月6日	所检项目合格	 A worker wearing a grey uniform and a red hard hat is inspecting a piece of industrial equipment. The worker is leaning over the equipment, and the scene is set in an industrial environment. A timestamp '2023.4.21' is visible in the bottom right corner of the image.

44	GX-B1307/20-3-23016	2023年5月6日	所检项目合格	
45	GX-B1307/20-3-23017	2023年5月6日	所检项目合格	
46	GX-B1307/20-3-23018	2023年5月6日	所检项目合格	
47	GX-B1307/20-3-23019	2023年5月6日	所检项目合格	

48	GX-B1307/20-3-23020	2023年5月6日	所检项目合格	
49	GX-B1310/21-3-23035	2023. 5. 6	符合标准要求。	
50	GX-B1424/20-3-23002	2023年5月8日	依据NB/T 10176-2019单轨吊车综合判定合格。	
51	GX-B1424/20-3-23003	2023年5月8日	依据NB/T 10176-2019单轨吊车综合判定合格。	





52	GX-B1424/20-3-23004	2023年5月8日	依据NB/T 10176-2019单轨吊车综合判定合格。	
53	GX-B1424/20-3-23005	2023年5月8日	依据NB/T 10176-2019单轨吊车综合判定合格。	
54	GX-B1328/20-3-23117	2023年5月8日	本次共检绝缘手套66只，66只绝缘手套合格。	
55	GX-B1328/20-3-23118	2023年5月8日	本次共检绝缘鞋66只，66只绝缘鞋合格。	

56	GX-B1328/20-3-23136	2023年5月8日	本次共检绝缘鞋6只，6只绝缘鞋合格。	
57	GX-B1321/20-3-23812 ~ 23822	2023年5月9日	本次共检电力电缆11条，11条电力电缆所检项目合格。	
58	GX-B1321/20-3-23823 ~ 23833	2023年5月9日	本次共检电力电缆11条，11条电力电缆所检项目合格。	
59	GX-B1321/20-3-23834 ~ 23847	2023年5月9日	本次共检电力电缆14条，14条电力电缆所检项目合格。	

60	GX-B1321/20-3-23848 ~ 23860	2023年5月9日	本次共检电力电缆13条，13条电力电缆所检项目合格。			
61	GX-B1321/20-3-23861 ~ 23874	2023年5月9日	本次共检电力电缆14条，14条电力电缆所检项目合格。			
62	GX-B1321/20-3-23875 ~ 23887	2023年5月9日	本次共检电力电缆13条，13条电力电缆所检项目合格。			
63	GX-B1321/20-3-23888 ~ 23902	2023年5月9日	本次共检电力电缆15条，15条电力电缆所检项目合格。			

64	GX-B1321/20-3-23903 ~ 23917	2023年5月9日	本次共检电力电缆15条，15条电力电缆所检项目合格。		
65	GX-B1321/20-3-23918 ~ 23930	2023年5月9日	本次共检电力电缆13条，13条电力电缆所检项目合格。		
66	GX-B1312/20-3-23287 ~ 23290	2023年5月9日	本次共检测电力变压器4台，4台电力变压器所检项目合格。		
67	GX-B1312/20-3-23291 ~ 23300	2023年5月9日	本次共检测电力变压器10台，10台电力变压器所检项目合格。		

68	GX-B1312/20-3-23301 ~ 23307	2023年5月9日	本次共检测电力变压器7台，7台电力变压器所检项目合格。		
69	GX-B1312/20-3-23308 ~ 23314	2023年5月9日	本次共检测电力变压器7台，7台电力变压器所检项目合格。		
70	GX-B1312/20-3-23315 ~ 23323	2023年5月9日	本次共检测电力变压器9台，9台电力变压器所检项目合格。		
71	GX-B1312/20-3-23324 ~ 23330	2023年5月9日	本次共检测电力变压器7台，7台电力变压器所检项目合格。		

72	GX-B1312/20-3-23331 ~ 23338	2023年5月9日	本次共检测电力变压器8台，8台电力变压器所检项目合格。			
73	GX-B1323/21-3-23137-23144	2023年5月9日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。			
74	GX-B1323/21-3-23145-23152	2023年5月9日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。			
75	GX-B1323/21-3-23153-23160	2023年5月9日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。			

76	GX-B1339/21-3-23001	2023年5月11日	所检项目合格。	 A worker in a white uniform and red helmet is inspecting a large green industrial tank. The worker is leaning over the tank, and the scene is set in an industrial facility. A timestamp '2023.4.5' is visible in the bottom right corner of the image.
77	GX-B1339/21-3-23002	2023年5月11日	所检项目合格。	 A worker in a white uniform and red helmet is inspecting a large industrial motor. The worker is kneeling on the ground, and the motor is mounted on a concrete base. The scene is set in an industrial facility. A timestamp '2023.4.5' is visible in the bottom right corner of the image.
78	GX-B1339/21-3-23003	2023年5月11日	所检项目合格。	 A worker in a white uniform and red helmet is inspecting a green industrial tank. The worker is kneeling on the ground, and the tank is part of a larger industrial system. The scene is set in an industrial facility. A timestamp '2023.4.5' is visible in the bottom right corner of the image.
79	GX-B1339/21-3-23004	2023年5月11日	所检项目合格。	 Two workers in white uniforms and red helmets are inspecting a large orange industrial tank. The workers are standing in front of the tank, and the scene is set in an outdoor industrial facility. A timestamp '2023.4.5' is visible in the bottom right corner of the image.

80	GX-B1339/21-3-23005	2023年5月11日	所检项目合格。	 A worker wearing a grey jacket and a red helmet is standing next to a large orange pipe. The worker is holding a blue device, possibly a detector or measuring instrument, against the pipe. The background shows some greenery. A small timestamp '2023.4.5' is visible in the bottom right corner of the image.
81	GX-B1339/21-3-23006	2023年5月11日	所检项目合格。	 A worker wearing a grey jacket and a red helmet is kneeling on the ground, inspecting a blue machine. The worker is holding a device, possibly a detector or measuring instrument, against the machine. The background shows some concrete and other equipment. A small timestamp '2021.4.5' is visible in the bottom right corner of the image.