


序号	报告编号	发布日期	结论	影像资料
779	GX-B1306/21-Y-23083	2023年6月27日	所检项目合格。	
780	GX-B1306/21-Y-23084	2023年6月27日	所检项目合格。	

781	GX-B1306/21-Y-23085	2023年6月27日	所检项目合格。	 <p>A photograph showing a worker in a grey uniform and red helmet standing next to a large, light-colored industrial cabinet. The worker is holding a clipboard and looking at the cabinet. A yellow timestamp '2023/5/21' is visible in the bottom right corner of the image.</p>
782	GX-B1306/21-Y-23097	2023年6月27日	所检项目合格。	 <p>A photograph showing a worker in a blue uniform and red helmet standing next to a large, dark-colored industrial machine. The worker is holding a clipboard and looking at the machine. A yellow timestamp '2023/6/4' is visible in the bottom right corner of the image.</p>

783	GX-B1306/21-Y-23098	2023年6月27日	所检项目合格。	
784	GX-B1306/21-Y-23099	2023年6月27日	所检项目合格。	

785	GX-B1306/21-Y-23100	2023年6月27日	所检项目合格。	
786	GX-B1306/21-Y-23101	2023年6月27日	所检项目合格。	

787	GX-B1306/21-Y-23102	2023年6月27日	所检项目合格。	 A photograph showing a worker in a blue uniform and red helmet inspecting a large industrial machine. The machine is white with blue accents and has a control panel with various buttons and indicators. The worker is holding a tool or device. The date '2023/6/4' is visible in the bottom right corner of the photo.
788	GX-B1306/21-Y-23103	2023年6月27日	所检项目合格。	 A photograph showing a worker in a blue uniform and red helmet inspecting a large industrial machine. The machine is white with blue accents and has a control panel with various buttons and indicators. The worker is holding a tool or device. The date '2023/6/4' is visible in the bottom right corner of the photo.

789	GX-B1521/20-Y-23308	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
790	GX-B1521/20-Y-23309	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

791	GX-B1521/20-Y-23310	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
792	GX-B1521/20-Y-23311	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

793	GX-B1521/20-Y-23312	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
794	GX-B1521/20-Y-23313	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

795	GX-B1521/20-Y-23314	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
796	GX-B1521/20-Y-23315	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

797	GX-B1521/20-Y-23316	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
798	GX-B1521/20-Y-23317	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

799	GX-B1521/20-Y-23318	2023年6月28日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
800	GX-B1521/20-Y-23319	2023年6月28日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

801	GX-B1521/20-Y-23320	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
802	GX-B1521/20-Y-23321	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

803	GX-B1521/20-Y-23322	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
804	GX-B1521/20-Y-23323	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

805	GX-B1521/20-Y-23324	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
806	GX-B1521/20-Y-23325	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

807	GX-B1521/20-Y-23326	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
808	GX-B1521/20-Y-23327	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

809	GX-B1521/20-Y-23328	2023年6月28日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	 A red LCMG ME130 hydraulic excavator is shown in operation on a construction site. The excavator is positioned on a dirt surface, and its arm is extended. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the image.
810	GX-B1310/21-Y-23097	2023年6月27日	符合标准要求。	 A worker wearing a blue uniform and a red helmet with a headlamp is operating machinery. The worker is focused on a task, possibly inspecting or adjusting a component. A yellow timestamp '2023/5/24' is visible in the bottom right corner of the image.

811	GX-B1310/21-Y-23092	2023年6月27日	符合标准要求。	
812	GX-B1428/21-Y-23092	2023年6月27日	无缺陷迹痕显示。	

813	GX-B1417/22-Y-23054	2023年6月30日	综合判定：合格。	
814	GX-B1417/22-Y-23055	2023年6月30日	综合判定：合格。	

815	GX-B1417/22-Y-23056	2023年6月30日	综合判定：合格。	
816	GX-B1417/22-Y-23057	2023年6月30日	综合判定：合格。	

817	GX-B1417/22-Y-23058	2023年6月30日	综合判定：合格。	
818	GX-B1417/22-Y-23059	2023年6月30日	综合判定：合格。	

819	GX-B1417/22-Y-23060	2023年6月30日	综合判定：合格。	
820	GX-B1417/22-Y-23061	2023年6月30日	综合判定：合格。	

821	GX-B1417/22-Y-23062	2023年6月30日	综合判定：合格。	 <p>2023.6.1</p>
822	GX-B1417/22-Y-23063	2023年6月30日	综合判定：合格。	 <p>2023.6.1</p>

823	GX-B1417/22-Y-23064	2023年6月30日	综合判定：合格。	 <p>2023/6/31</p>
824	GX-B1417/22-Y-23065	2023年6月30日	综合判定：合格。	 <p>2023/5/31</p>

825	GX-B1417/22-Y-23066	2023年6月30日	综合判定：合格。	 <p>A photograph showing three workers in safety gear (hard hats and work clothes) standing in front of a white truck. The truck has a yellow number '6' on its front. The background shows a clear blue sky and some industrial buildings. A yellow timestamp '2023/6/31' is visible in the bottom right corner of the photo.</p>
826	GX-B1417/22-Y-23067	2023年6月30日	综合判定：合格。	 <p>A photograph showing three workers in safety gear (hard hats and work clothes) standing in front of a white truck. The truck has a blue license plate. The background shows a clear blue sky and some industrial buildings. A yellow timestamp '2023/6/31' is visible in the bottom right corner of the photo.</p>

827	GX-B1417/22-Y-23068	2023年6月30日	综合判定：合格。	
828	GX-B1417/22-Y-23069	2023年6月30日	综合判定：合格。	

829	GX-B1417/22-Y-23070	2023年6月30日	综合判定：合格。	 A photograph showing two men standing next to a white utility vehicle, possibly a forklift or a small truck, in an outdoor setting. The vehicle has some red text on its side. A yellow timestamp '2023/6/4' is visible in the bottom right corner of the image.
830	GX-B1414/22-Y-23001	2023年6月30日	所检项目合格。	 A photograph showing a worker in a blue uniform and a red hard hat operating a piece of machinery, possibly a forklift or a similar vehicle, in an outdoor setting. A yellow timestamp '2023/6/4' is visible in the bottom right corner of the image.



831	GX-B1495/20-Y-231482~231490	2023年6月27日	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	
832	GX-B1495/20-Y-231491~231499	2023年6月27日	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	

833	GX-B1495/20-Y-231500~231510	2023年6月27日	本次共检高压防爆开关11台，11台高压防爆开关所检项目合格。	
834	GX-B1385/21-Y-23074	2023年6月30日	所检项目合格。	

835	GX-B1385/21-Y-23075	2023年6月30日	所检项目合格。	 A worker wearing a blue uniform and a red helmet is inspecting a cable in a tunnel. The worker is holding a clipboard and looking at the cable. The background shows the interior of a tunnel with some equipment and lights. A yellow timestamp '2023/5/23' is visible in the bottom right corner of the image.
836	GX-B1321/20-Y-23533~23537	2023年6月30日	本次共检电力电缆5条， 5条电力电缆所检项目合格。	 A worker wearing a blue uniform and a red helmet is inspecting cables in a tunnel. The worker is kneeling and looking at the cables. The background shows the interior of a tunnel with many cables and some equipment. A yellow timestamp '2023/5/23' is visible in the bottom right corner of the image.

837	GX-B1321/20-Y-23538~23543	2023年6月30日	本次共检电力电缆6条， 6条电力电缆所检项目合格。	
838	GX-B1321/20-Y-23544~23549	2023年6月30日	本次共检电力电缆6条， 6条电力电缆所检项目合格。	

839	GX-B1328/20-Y-23069	2023年6月30日	本次共检绝缘手套 37只，37只绝缘手套所 检项目合格。	
840	GX-B1328/20-Y-23070	2023年6月30日	本次共检绝缘鞋28只， 28只绝缘鞋所检项目合 格。	

841	GX-B1328/20-Y-23071	2023年6月30日	本次共检验电器7支，7支验电器所检项目合格。	 A photograph showing an outdoor electrical inspection site. A worker in a grey shirt and red helmet is kneeling on the ground, operating a piece of equipment. Another worker in a blue shirt and red helmet is standing nearby. The ground is concrete and there are some tools and equipment scattered around. A date stamp '2023/5/21' is visible in the bottom right corner of the photo.
842	GX-B1328/20-Y-23072	2023年6月30日	本次共检接地装置7组，7组接地装置所检项目合格。	 A photograph showing an outdoor electrical inspection site. A worker in a grey shirt and red helmet is kneeling on the ground, operating a piece of equipment. Another worker in a blue shirt and red helmet is standing nearby. The ground is concrete and there are some tools and equipment scattered around. A date stamp '2023/5/21' is visible in the bottom right corner of the photo.

843	GX-B1301/21-Y-23001	2023年6月30日	综合判定:合格。	 A photograph showing a male worker wearing a red hard hat and a grey long-sleeved uniform. He is standing and operating a large green industrial machine. The machine has yellow accents and a yellow circle with the number '0' on it. A date stamp '2023/5/20' is visible in the bottom right corner of the photo.
844	GX-B1300/20-Y-23007	2023年6月30日	综合判定:合格。	 A photograph showing a male worker wearing a red hard hat and a grey long-sleeved uniform. He is kneeling on a blue platform, working on a green industrial machine. The machine has a yellow square with the number '8' on it. Another worker in a red hard hat is partially visible in the background. A date stamp '2023/5/20' is visible in the bottom right corner of the photo.

845	GX-B1300/20-Y-23006	2023年6月30日	综合判定:合格。	
846	GX-B1310/21-Y-23091	2023年6月30日	符合标准要求。	

847	GX-B1428/21-Y-23091	2023年6月30日	无缺陷迹痕显示。	
848	GX-B1310/21-Y-23088	2023年6月30日	符合标准要求。	

849	GX-B1427/21-Y-23088	2023年6月30日	符合标准要求。	
850	GX-B1310/21-Y-23093	2023年6月30日	符合标准要求。	