

序号	报告编号	发布日期	结论	影像资料
183	GX-B1310/21-6-23104	2023/8/10	符合标准要求	
184	GX-B1427/21-6-23058	2023/8/10	符合标准要求	
185	GX-B1423/20-6-23795	2023/8/10	综合判定合格	

186	GX-B1423/20-6-23796	2023/8/10	综合判定合格	
187	GX-B1423/20-6-23797	2023/8/10	综合判定合格	
188	GX-B1423/20-6-23798	2023/8/10	综合判定合格	

189	GX-B1423/20-6-23799	2023/8/10	综合判定合格	 A photograph showing two workers wearing red hard hats and work clothes standing next to a large yellow SANY truck. The truck has 'SANY' written on its side. The date '2023 7 20' is visible in the bottom right corner of the image.
190	GX-B1423/20-6-23800	2023/8/10	综合判定合格	 A photograph showing two workers wearing red hard hats and work clothes standing next to a large yellow SANY truck. The truck has 'SANY' written on its side. The date '2023 7 20' is visible in the bottom right corner of the image.
191	GX-B1517/20-6-23004	2023/8/9	综合判定：合格	 A photograph showing a worker wearing a red hard hat and blue work clothes crouching next to a large red piece of machinery. The worker is holding a tool. The date '2023 06 03' is visible in the bottom right corner of the image.

192	GX-B1517/20-6-23005	2023/8/9	综合判定：合格	
193	GX-B1517/20-6-23006	2023/8/9	综合判定：合格	
194	GX-B1517/20-6-23007	2023/8/9	综合判定：合格	

195	GX-B1517/20-6-23008	2023/8/9	综合判定：合格	
196	GX-B1423/20-6-23801	2023/8/11	综合判定合格	
197	GX-B1423/20-6-23802	2023/8/11	综合判定合格	

198	GX-B1423/20-6-23803	2023/8/11	综合判定合格		
199	GX-B1423/20-6-23804	2023/8/11	综合判定合格		
200	GX-B1423/20-6-23788	2023/8/11	综合判定合格		

201	GX-B1423/20-6-23789	2023/8/11	综合判定合格		
202	GX-B1423/20-6-23790	2023/8/11	综合判定合格		
203	GX-B1423/20-6-23791	2023/8/11	综合判定合格		

204	GX-B1423/20-6-23792	2023/8/11	综合判定合格		
205	GX-B1423/20-6-23793	2023/8/11	综合判定合格		
206	GX-B1423/20-6-23794	2023/8/11	综合判定合格		

207	GX-B1520/20-6-23093	2023/8/11	综合判定合格		
208	GX-B1350/21-6-23044	2023/8/14	所检项目合格		
209	GX-B1350/21-6-23045	2023/8/14	所检项目合格		

210	GX-B1428/21-6-23030	2023/8/14	无缺陷迹痕显示	
211	GX-B1300/20-6-23007	2023/8/14	综合判定：合格。 。	
212	GX-B1300/20-6-23006	2023/8/14	综合判定：合格。 。	

213	GX-B1500/21-6-23121	2023/8/14	综合判定：合格。 。		
214	GX-B1500/21-6-23122	2023/8/14	综合判定：合格。 。		
215	GX-B1500/21-6-23123	2023/8/14	综合判定：合格。 。		

216	GX-B1500/21-6-23124	2023/8/14	综合判定：合格。 。		
217	GX-B1309/21-6-23034	2023/8/14	所检项目合格。		
218	GX-B1598/21-6-23014	2023/8/11	实测钢丝绳有效 截面积损失百分 比最大为 0.53%，小于5% 为正常。		

219	GX-B1598/21-6-23015	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.53%，小于6%为正常。		
220	GX-B1598/21-6-23016	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.53%，小于7%为正常。		
221	GX-B1598/21-6-23017	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.53%，小于8%为正常。		


222	GX-B1598/21-6-23018	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.53%，小于9%为正常。	
223	GX-B1598/21-6-23019	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.53%，小于10%为正常。	
224	GX-B1300/20-6-23008	2023/8/14	综合判定合格	

225	GX-B1598/21-6-23014	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.53%，小于5%为正常。		
226	GX-B1598/21-6-23015	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.34%，小于5%为正常。		
227	GX-B1598/21-6-23016	2023/8/11	实测钢丝绳有效截面损失百分比最大为0.63%，小于5%为正常。		

228	GX-B1598/21-6-23017	2023/8/11	<p>实测钢丝绳有效截面损失百分比最大为0.54%，小于5%为正常。</p>	
229	GX-B1598/21-6-23018	2023/8/11	<p>实测钢丝绳有效截面损失百分比最大为1.38%，小于5%为正常。</p>	
230	GX-B1598/21-6-23019	2023/8/11	<p>实测钢丝绳有效截面损失百分比最大为1.99%，小于5%为正常。</p>	

231	GX-B1300/20-6-23008	2023/8/14	综合判定合格	 A photograph showing two workers wearing red hard hats and light-colored shirts. They are standing next to a large green industrial machine, possibly a hoist or winch, in an indoor setting. The date stamp in the bottom right corner of the photo is 2023 08 08.
232	GX-B1423/20-6-23817	2023/8/14	综合判定合格	 A photograph of a yellow MT80H truck parked on a paved surface. Two workers are standing in front of the truck. The date stamp in the bottom right corner of the photo is 2023 08 08.
233	GX-B1598/21-6-23020	2023/8/11	实测钢丝绳有效 截面积损失百分 比最大为 2.15%，小于5% 为正常	 A photograph showing a worker in a red hard hat and blue overalls inspecting a large steel cable. The worker is on a yellow metal platform or lift. The date stamp in the bottom right corner of the photo is 2023 07 20.

234	GX-B1598/21-6-23021	2023/8/11	实测钢丝绳有效截面损失百分比最大为2.92%，小于5%为正常	
235	GX-B1598/21-6-23022	2023/8/11	实测钢丝绳有效截面损失百分比最大为2.25%，小于5%为正常	
236	GX-B1598/21-6-23023	2023/8/11	实测钢丝绳有效截面损失百分比最大为1.86%，小于5%为正常	

237	GX-B1598/21-6-23024	2023/8/11	<p>实测钢丝绳有效 截面积损失百分 比最大为 3.96%，小于5% 为正常</p>		
238	GX-B1598/21-6-23025	2023/8/11	<p>实测钢丝绳有效 截面积损失百分 比最大为 3.13%，小于5% 为正常</p>		
239	GX-B1598/21-6-23026	2023/8/11	<p>实测钢丝绳有效 截面积损失百分 比最大为 2.93%，小于5% 为正常</p>		



240	GX-B1598/21-6-23027	2023/8/11	<p>实测钢丝绳有效 截面积损失百分 比最大为 2.56%，小于5% 为正常</p>	
241	GX-B1598/21-6-23028	2023/8/11	<p>实测钢丝绳有效 截面积损失百分 比最大为 2.59%，小于5% 为正常</p>	
242	GX-B1598/21-6-23029	2023/8/11	<p>实测钢丝绳有效 截面积损失百分 比最大为 2.89%，小于5% 为正常</p>	

243	GX-B1598/21-6-23030	2023/8/11	实测钢丝绳有效截面损失百分比最大为3.62%，小于5%为正常			
244	GX-B1598/21-6-23031	2023/8/11	实测钢丝绳有效截面损失百分比最大为3.57%，小于5%为正常			
245	GX-B1323/21-6-23236~23239	2023/8/14	所检项目合格			

246	GX-B1321/20-6-23775~23776	2023/8/14	所检项目合格	 <p>2023 08 08</p>
247	GX-B1314/21-6-23001~23003	2023/8/14	所检项目合格	 <p>2023 08 08</p>
248	GX-B1322/21-6-23276	2023/8/14	所检项目合格	 <p>2023 08 08</p>

249	GX-B1313/21-6-23229	2023/8/14	所检项目合格		
250	GX-B1423/20-6-23835	2023/8/18	综合判定合格		
251	GX-B1423/20-6-23836	2023/8/18	综合判定合格		

252	GX-B1423/20-6-23837	2023/8/18	综合判定合格	
253	GX-B1423/20-6-23838	2023/8/18	综合判定合格	
254	GX-B1423/20-6-23839	2023/8/18	综合判定合格	

255	GX-B1423/20-6-23818	2023/8/18	综合判定合格	 A photograph of a red truck with its driver-side door open. Two men are standing in front of the truck on a dirt road. The man on the left is wearing a grey t-shirt and dark pants, while the man on the right is wearing a light blue shirt, dark pants, and a red hard hat. The truck has 'PENTON' written on the front and a yellow license plate. A date stamp '2023 08 18' is visible in the bottom right corner of the photo.
256	GX-B1423/20-6-23819	2023/8/18	综合判定合格	 A photograph of a red truck with its driver-side door open. Two men are standing in front of the truck on a dirt road. The man on the left is wearing a light blue shirt, dark pants, and a red hard hat. The man on the right is wearing a white t-shirt and patterned shorts. The truck has 'PENTON' written on the front and a yellow license plate. A date stamp '2023 08 18' is visible in the bottom right corner of the photo.
257	GX-B1423/20-6-23820	2023/8/18	综合判定合格	 A photograph of a red truck with its driver-side door open. Two men are standing in front of the truck on a dirt road. The man on the left is wearing a light blue shirt, dark pants, and a red hard hat. The man on the right is wearing a dark t-shirt and dark pants. The truck has 'PENTON' written on the front and a yellow license plate. A date stamp '2023 08 18' is visible in the bottom right corner of the photo.

258	GX-B1423/20-6-23821	2023/8/18	综合判定合格	 <p>A photograph of a red truck parked on a dirt road. A person wearing a red hard hat and a light blue shirt is standing to the left of the truck. The truck is a large, heavy-duty vehicle with a white cargo area. The date '2023 08 18' is visible in the bottom right corner of the photo.</p>
259	GX-B1423/20-6-23822	2023/8/18	综合判定合格	 <p>A photograph showing two people standing in front of a red truck. The person on the left is wearing a red hard hat and a light blue shirt, while the person on the right is wearing a white t-shirt. The truck is a red cab with a white trailer. The date '2023 08 18' is visible in the bottom right corner of the photo.</p>
260	GX-B1423/20-6-23823	2023/8/18	综合判定合格	 <p>A photograph of two people standing in front of a green truck. The person on the left is wearing a red hard hat and a light blue shirt, and the person on the right is wearing a black t-shirt. The truck is a green cab with a white trailer. The date '2023 08 18' is visible in the bottom right corner of the photo.</p>

261	GX-B1423/20-6-23824	2023/8/18	综合判定合格	
262	GX-B1423/20-6-23825	2023/8/18	综合判定合格	
263	GX-B1423/20-6-23826	2023/8/18	综合判定合格	

264	GX-B1423/20-6-23827	2023/8/18	综合判定合格		
265	GX-B1423/20-6-23828	2023/8/18	综合判定合格		
266	GX-B1423/20-6-23829	2023/8/18	综合判定合格		

267	GX-B1423/20-6-23830	2023/8/18	综合判定合格	
268	GX-B1423/20-6-23831	2023/8/18	综合判定合格	
269	GX-B1423/20-6-23832	2023/8/18	综合判定合格	

270	GX-B1423/20-6-23833	2023/8/18	综合判定合格		
271	GX-B1423/20-6-23834	2023/8/18	综合判定合格		
272	GX-B1322/21-6-23276	2023/8/14	所检项目合格。		

273	GX-B1313/21-6-23229	2023/8/14	所检项目合格。		
274	GX-B1309/21-6-23034	2023/8/14	所检项目合格		
275	GX-B1500/21-6-23121	2023/8/14	综合判定：合格。 。		

276	GX-B1500/21-6-23122	2023/8/14	综合判定：合格。 。		
277	GX-B1500/21-6-23123	2023/8/14	综合判定：合格。 。		
278	GX-B1500/21-6-23124	2023/8/14	综合判定：合格。 。		

