

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|------------|---------|---|
| 1 | GX/B1310-21-P-23128 | 2023. 9. 4 | 符合标准要求。 |  A photograph showing a worker in a white shirt and red helmet performing maintenance or inspection on industrial machinery. The worker is standing on a platform or scaffolding, and the machinery is complex with various pipes and structures. A timestamp '2023.8.13' is visible in the bottom right corner of the image. |
| 2 | GX/B1310-21-P-23129 | 2023. 9. 4 | 符合标准要求。 |  A photograph showing a worker in a blue shirt and red helmet using a handheld device to inspect machinery. The worker is wearing a red helmet and a blue shirt, and is holding a device that displays some information. The machinery is industrial and complex. A timestamp '2023.8.13' is visible in the bottom right corner of the image. |

| | | | | |
|---|---------------------|------------|---------|---|
| 3 | GX/B1427-21-P-23017 | 2023. 9. 4 | 符合标准要求。 |  <p>2023.8.13</p> |
| 4 | GX/B1427-21-P-23018 | 2023. 9. 4 | 符合标准要求。 |  <p>2023.8.13</p> |
| 5 | GX-B1313/21-P-23017 | 2023. 9. 6 | 所检项目合格。 |  <p>2023.8.12</p> |

| | | | | |
|---|---------------------|------------|---------|---|
| 6 | GX-B1427/21-P-23019 | 2023. 9. 2 | 符合标准要求。 |  <p>2023.6.16</p> |
| 7 | GX-B1427/21-P-23020 | 2023. 9. 2 | 符合标准要求。 |  <p>2023.6.19</p> |
| 8 | GX-B1310/21-P-23130 | 2023. 9. 2 | 符合标准要求。 |  <p>2023.6.16</p> |

| | | | | |
|----|---------------------|------------|---------|---|
| 9 | GX-B1310/21-P-23131 | 2023. 9. 2 | 符合标准要求。 |  A photograph showing two workers in safety gear (hard hats and high-visibility vests) standing in an industrial or construction setting. The date stamp '2023.6.19' is visible in the bottom right corner of the image. |
| 10 | GX-B1423/20-P-23034 | 2023. 9. 2 | 综合判定：合格 |  A photograph showing a person wearing a red hard hat operating a yellow vehicle, possibly a forklift or loader. The date stamp '2023.8.12' is visible in the bottom right corner of the image. |
| 11 | GX-B1423/20-P-23035 | 2023. 9. 2 | 综合判定：合格 |  A photograph showing a person wearing a red hard hat operating a yellow vehicle, possibly a forklift or loader. The date stamp '2023.8.12' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------|------------|---------|--|
| 12 | GX-B1423/20-P-23036 | 2023. 9. 2 | 综合判定：合格 |  |
| 13 | GX-B1423/20-P-23037 | 2023. 9. 2 | 综合判定：合格 |  |
| 14 | GX-B1423/20-P-23038 | 2023. 9. 2 | 综合判定：合格 |  |

| | | | | |
|----|---------------------|------------|---------|---|
| 15 | GX-B1423/20-P-23039 | 2023. 9. 2 | 综合判定：合格 |  |
|----|---------------------|------------|---------|---|