

序号	报告编号	发布日期	结论	影像资料
244	GX-B1303/21-6-23019	2023. 10. 26	合格	
245	GX-B1310/21-6-23163	2023/10/26	符合标准要求	

246	GX-B1310/21-6-23164	2023/10/26	符合标准要求	
247	GX-B1310/21-6-23165	2023/10/26	符合标准要求	
248	GX-B1310/21-6-23166	2023/10/26	符合标准要求	

249	GX-B1310/21-6-23167	2023/10/26	符合标准要求	 A worker in a blue uniform and red hard hat is inspecting a large, dark industrial component, possibly a valve or part of a machine. The worker is holding a tool or device. The background shows an industrial setting with other equipment. A yellow timestamp '2023 10 6' is visible in the bottom right corner of the photo.
250	GX-B1427/21-6-23089	2023/10/26	符合标准要求	 A worker in a grey uniform and red hard hat is inspecting a large, dark industrial component, similar to the one in the first photo. The worker is holding a tool or device. The background shows an industrial setting. A yellow timestamp '2023 10 6' is visible in the bottom right corner of the photo.
251	GX-B1329/21-6-23103~23108	2023/10/24	所检项目合格	 A worker in a black uniform and white hard hat is working on a control panel or electrical equipment. The worker is kneeling and using a tool. The background shows an industrial setting with various equipment. A yellow timestamp '2023 09 14' is visible in the bottom right corner of the photo.

252	GX-B1423/20-6-231076	2023/10/27	综合判定合格		
253	GX-B1423/20-6-231077	2023/10/27	综合判定合格		
254	GX-B1423/20-6-231078	2023/10/27	综合判定合格		

255	GX-B1423/20-6-231079	2023/10/27	综合判定合格	
256	GX-B1423/20-6-231080	2023/10/27	综合判定合格	
257	GX-B1423/20-6-231081	2023/10/27	综合判定合格	

258	GX-B1380/20-6-23039	2023/10/30	所检项目合格	
259	GX-B1423/20-6-231059	2023/10/30	综合判定合格	
260	GX-B1423/20-6-231060	2023/10/30	综合判定合格	

261	GX-B1423/20-6-231061	2023/10/30	综合判定合格	 A yellow truck is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The truck has a Mercedes-Benz logo on the front. A small timestamp '2023 10 16' is visible in the bottom right corner of the photo.
262	GX-B1423/20-6-231062	2023/10/30	综合判定合格	 A yellow truck is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. A red ribbon is tied across the front of the truck. The truck has a Mercedes-Benz logo on the front. A small timestamp '2023 10 16' is visible in the bottom right corner of the photo.
263	GX-B1423/20-6-231063	2023/10/30	综合判定合格	 A yellow truck is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. A red ribbon is tied across the front of the truck. The truck has a Mercedes-Benz logo on the front. A small timestamp '2023 10 16' is visible in the bottom right corner of the photo.

264	GX-B1423/20-6-231064	2023/10/30	综合判定合格	
265	GX-B1423/20-6-231065	2023/10/30	综合判定合格	
266	GX-B1423/20-6-231066	2023/10/30	综合判定合格	

267	GX-B1423/20-6-231067	2023/10/30	综合判定合格	
268	GX-B1423/20-6-231068	2023/10/30	综合判定合格	
269	GX-B1423/20-6-231069	2023/10/30	综合判定合格	

270	GX-B1423/20-6-231070	2023/10/30	综合判定合格	
271	GX-B1423/20-6-231071	2023/10/30	综合判定合格	
272	GX-B1423/20-6-231072	2023/10/30	综合判定合格	

273	GX-B1423/20-6-231073	2023/10/30	综合判定合格	 <p>2023 10 17</p>
274	GX-B1423/20-6-231074	2023/10/30	综合判定合格	 <p>2023 10 17</p>
275	GX-B1423/20-6-231075	2023/10/30	综合判定合格	 <p>2023 10 17</p>

276	GX-B1515/22-6-23018	2023/10/31	所检项目合格	
277	GX-B1310/21-6-23153	2023/10/31	符合标准要求	
278	GX-B1310/21-6-23154	2023/10/31	符合标准要求	

279	GX-B1310/21-6-23155	2023/10/28	符合标准要求		
280	GX-B1307/20-6-23051	2023/10/31	综合判定：合格。		
281	GX-B1307/20-6-23052	2023/10/31	综合判定：合格。		

282	GX-B1307/20-6-23053	2023/10/31	综合判定：合格。	
283	GX-B1307/20-6-23054	2023/10/31	综合判定：合格。	
284	GX-B1307/20-6-23055	2023/10/31	综合判定：合格。	

285	GX-B1307/20-6-23056	2023/10/31	综合判定：合格。	
286	GX-B1307/20-6-23057	2023/10/31	综合判定：合格。	
287	GX-B1307/20-6-23058	2023/10/31	综合判定：合格。	

288	GX-B1451/20-6-23684~23690	2023/10/30	所检项目合格	 <p>2023 10 05</p>
289	GX-B1424/20-6-23017	2023/10/31	依据NB/T 10176-2019单轨吊车综合判定合格	 <p>2023 09 18</p>
290	GX-B1424/20-6-23020	2023/10/31	依据NB/T 10176-2019单轨吊车综合判定合格	 <p>2023 10 11</p>

291	GX-B1424/20-6-23018	2023/10/31	依据NB/T 10176-2019单轨吊车综合判定合格		
292	GX-B1424/20-6-23019	2023/10/31	依据NB/T 10176-2019单轨吊车综合判定合格		
293	GX-B1322/21-6-23301~23006	2023/10/23	所检项目合格		

294	GX-B1328/20-6-23146	2023/10/31	所检项目合格		
295	GX-B1328/20-6-23147	2023/10/31	所检项目合格		
296	GX-B1328/20-6-23148	2023/10/31	所检项目合格		

297	GX-B1328/20-6-23149	2023/10/31	所检项目合格	
-----	---------------------	------------	--------	---