

序号	报告编号	发布日期	结论	影像资料
38	GX-B1517/20-5-23029	2023. 11. 28	综合判定：合格	
39	:GX-B1495/20-5-231758~231775	2023/11/30	所检项目合格	

40	GX-B1329/21-5-23190~23200	2023/11/30	本次共检氧化锌避雷器11组，11组氧化锌避雷器所检项目合格。 。	 A photograph showing a worker in a red hard hat and light blue shirt working on a piece of equipment. The worker is holding a red and green wire. The equipment is a metal cabinet with a control panel. A yellow date stamp '2023.09.13' is visible in the bottom right corner of the photo.
41	GX-B1329/21-5-23201~23216	2023/11/30	本次共检氧化锌避雷器16组，16组氧化锌避雷器所检项目合格。 。	 A photograph showing a worker in a red hard hat and white shirt working on a piece of equipment. The worker is holding a red and green wire. The equipment is a metal cabinet with a control panel. A yellow date stamp '2023.09.14' is visible in the bottom right corner of the photo.

42	GX-B1339/21-5-23008	2023. 11. 30	所检项目合格。	
----	---------------------	--------------	---------	---