



序号	报告编号	发布日期	结论	影像资料
126	GX-B1557/22-Y-24003	2024年1月31日	所检项目合格。	
127	GX-B1557/22-Y-24005	2024年2月19日	所检项目合格。	

128	GX-B1521/20-Y-24067	2024年2月19日	所检项目合格。	 A photograph showing a person wearing a yellow jacket and a dark hat, operating a piece of machinery, possibly a forklift or a similar industrial vehicle. The person is seated in the operator's compartment, and the machinery is visible in the background. A yellow timestamp "2024/2/2" is visible in the bottom right corner of the image.
129	GX-B1521/20-Y-24068	2024年2月19日	所检项目合格。	 A photograph showing a person wearing a yellow jacket and a dark hat, operating a piece of machinery, possibly a forklift or a similar industrial vehicle. The person is seated in the operator's compartment, and the machinery is visible in the background. A yellow timestamp "2024/2/2" is visible in the bottom right corner of the image.

130	GX-B1521/20-Y-24069	2024年2月19日	所检项目合格。	 A photograph showing a person wearing a dark hat, a heavy brown winter jacket, and white gloves. They are seated in the operator's seat of a vehicle, possibly a forklift or a similar piece of machinery. The person is looking towards the camera. The background shows a clear blue sky and parts of the vehicle's structure. A yellow timestamp '2024/2/19' is visible in the bottom right corner of the image.
131	GX-B1539/22-Y-24027	2024年2月20日	所检项目合格。	 A photograph showing a person wearing a dark hat, a heavy brown winter jacket, and white gloves. They are seated in the driver's seat of a vehicle, possibly a truck or a similar piece of machinery. The person is looking towards the camera. The background shows a clear blue sky and parts of the vehicle's interior and exterior. A yellow timestamp '2024/2/2' is visible in the bottom right corner of the image.

132	GX-B1539/22-Y-24028	2024年2月20日	所检项目合格。	 A photograph showing a worker wearing a heavy winter jacket and a fur-lined hat, operating a vehicle, likely a loader or excavator, in a snowy environment. The worker is holding a control lever. A yellow timestamp '2024/2/2' is visible in the bottom right corner of the image.
133	GX-B1495/20-Y-24015~24024	2024年2月21日	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	 A photograph showing a worker in a dark environment, possibly a mine or industrial facility, inspecting a piece of equipment, likely a high-voltage switch. The worker is using a flashlight to illuminate the equipment. A yellow timestamp '2024/1/18' is visible in the bottom right corner of the image.

134	GX-B1495/20-Y-24025~24031	2024年2月21日	本次共检高压防爆开关7台，7台高压防爆开关所检项目合格。	
135	GX-B1495/20-Y-24032~24044	2024年2月21日	本次共检高压开关柜13台，13台高压开关柜所检项目合格。	

136	GX-B1559/22-Y-24003	2024年2月21日	所检项目合格。	 <p>A photograph showing two men standing in front of a large yellow wheel loader inside a warehouse. The man on the left is wearing a blue jacket and a black cap, while the man on the right is wearing a dark jacket. The loader has a large front bucket and heavy-duty tires. A yellow timestamp '2024/1/28' is visible in the bottom right corner of the photo.</p>
137	GX-B1559/22-Y-24004	2024年2月21日	所检项目合格。	 <p>A photograph showing a worker in a white jacket and black cap operating a yellow wheel loader outdoors. The worker is sitting on the machine, looking at a device. The background shows a snowy landscape and a blue sky. A yellow timestamp '2024/1/28' is visible in the bottom right corner of the photo.</p>

138	GX-B1559/22-Y-24005	2024年2月21日	所检项目合格。	
139	GX-B1559/22-Y-24006	2024年2月21日	所检项目合格。	

140	GX-B1559/22-Y-24007	2024年2月21日	所检项目合格。	 <p>A photograph showing a worker wearing a red hard hat and a grey work jacket operating a piece of industrial machinery. The worker is seated on the machine, which has a white label with the number '01' on it. The date '2023/12/21' is visible in the bottom right corner of the photo.</p>
141	GX-B1559/22-Y-24008	2024年2月21日	所检项目合格。	 <p>A photograph showing a worker wearing a red hard hat and a grey work jacket standing next to a large piece of industrial machinery. The worker is standing on the ground, and the machinery has a white label with the number '6' on it. The date '2023/12/21' is visible in the bottom right corner of the photo.</p>

142	GX-B1559/22-Y-24009	2024年2月21日	所检项目合格。	
143	GX-B1328/20-Y-24020	2024年2月19日	本次共检验电器 28支，28支验电 器所检项目合格 。	

144	GX-B1328/20-Y-24021	2024年2月19日	本次共检携带式接地和接地短路装置30组，30组携带式接地和接地短路装置所检项目合格。	
145	GX-B1328/20-Y-24022	2024年2月19日	本次共检绝缘杆8支，8支绝缘杆所检项目合格。	

146	GX-B1328/20-Y-24016	2024年2月19日	本次共检绝缘杆5组，5组绝缘杆所检项目合格。	
147	GX-B1328/20-Y-24017	2024年2月19日	本次共检验电器28支，28支验电器所检项目合格。	

148	GX-B1328/20-Y-24026	2024年2月19日	本次共检绝缘手套102只，102只绝缘手套合格。	
149	GX-B1328/20-Y-24027	2024年2月19日	本次共检绝缘鞋86只，86只绝缘鞋合格。	

150	GX-B1328/20-Y-24024	2024年2月19日	本次共检验电器3支，3支验电器所检项目合格。	
151	GX-B1328/20-Y-24025	2024年2月19日	本次共检绝缘杆2组，2组绝缘杆所检项目合格。	