

序号	报告编号	发布日期	结论	影像资料
1	GX-B1559/22-P-24047	2024. 7. 5	所检项目合格。	 A worker wearing a red safety helmet, a blue face mask, and a light blue short-sleeved shirt is operating a piece of heavy machinery. The worker is holding a control lever. The background shows an outdoor industrial or construction site with a blue sky and some buildings. A timestamp '2024.6.13' is visible in the bottom right corner of the image.
2	GX-B1559/22-P-24048	2024. 7. 5	所检项目合格。	 A worker wearing a red safety helmet, a blue face mask, and a light blue short-sleeved shirt is operating a piece of heavy machinery. The worker is holding a control lever. The background shows an outdoor industrial or construction site with a blue sky and some buildings. A timestamp '2024.6.13' is visible in the bottom right corner of the image.
3	GX-B1559/22-P-24049	2024. 7. 5	所检项目合格。	 A worker wearing a red safety helmet, a blue face mask, and a light blue short-sleeved shirt is operating a piece of heavy machinery. The worker is holding a control lever. The background shows an outdoor industrial or construction site with a blue sky and some buildings. A timestamp '2024.6.13' is visible in the bottom right corner of the image.

4	GX-B1559/22-P-24050	2024. 7. 5	所检项目合格。			
5	GX-B1559/22-P-24051	2024. 7. 5	所检项目合格。			
6	GX-B1559/22-P-24052	2024. 7. 5	所检项目合格。			

7	GX-B1559/22-P-24053	2024. 7. 5	所检项目合格。	
8	GX-B1559/22-P-24054	2024. 7. 5	所检项目合格。	
9	GX-B1559/22-P-24055	2024. 7. 5	所检项目合格。	

10	GX-B1559/22-P-24056	2024. 7. 5	所检项目合格。	
11	GX-B1559/22-P-24057	2024. 7. 5	所检项目合格。	
12	GX-B1559/22-P-24058	2024. 7. 5	所检项目合格。	

13	GX-B1428/21-P-24010	2024. 7. 3	无缺陷痕迹显示。	
14	GX-B1310/21-P-24048	2024. 7. 3	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	